

**ITB 190501**

**Fire Extinguisher Services**

	<b>DACO Fire Equipment</b>
Fire Extinguisher Annual Inspection (per extinguisher)	<b>\$4.50</b>
Low Pressure Test (per extinguisher)	<b>\$15.00</b>
High Pressure Test (per extinguisher)	<b>\$20.00</b>
Recharge-ABC 2 ½ lbs.	<b>\$20.75</b>
Recharge- ABC 5 lbs.	<b>\$26.75</b>
Recharge-ABC 10 lbs.	<b>\$34.75</b>
Recharge-ABC 20 lbs.	<b>\$45.00</b>
Recharge- BC 2 ½ lbs.	<b>\$20.75</b>
Recharge-BC 5 lbs.	<b>\$26.75</b>
Recharge-BC 10 lbs.	<b>\$34.75</b>
Recharge-BC 20 lbs.	<b>\$45.00</b>
Recharge CO2 5 lbs.	<b>\$20.00</b>
Recharge CO2 10 lbs.	<b>\$30.00</b>
Recharge CO2 15 lbs.	<b>\$45.00</b>
Recharge CO2 20 lbs.	<b>\$60.00</b>
Recharge K 6 Liter Wet	<b>\$120.00</b>
Pressurized Water-2 1/2 gal	<b>\$15.00</b>

Pricing guaranteed August 1, 2019 through July 31, 2021

**Recommend award to DACO Fire Equipment.**